

OSŁONKI DO MALOWANIA PROSZKOWEGO

do 315 °C



KOD	KOLOR	POD GWINT	A	C	L
PBB600	czysty	M16	15,24	18,28	38,1
PBB625-750	czerwony	M16	15,88	18,92	19,05
PBB625-1125	czerwony	M16	15,88	18,92	28,58
PBB625-1250	czerwony	M16	15,88	18,92	31,75
PBB625	czerwony	M16	15,88	18,92	38,1
PBB625-2500	czerwony	M16	15,88	18,92	63,5
PBB687	zielona	M16	17,45	20,49	38,1
PBB687-2500	zielona	M16	17,45	20,49	63,5
PBB730	purpurowy	M16	18,54	21,58	38,1
PBB750	pomarańcz	M16	19,05	22,09	38,1
PBB750-2000	pomarańcz	M16	19,05	22,09	50,8
PBB750-3500	pomarańcz	M16	19,05	22,09	88,9
PBB780	czysty	M16	19,81	22,85	38,1
PBB812	czysty	M16	20,62	23,66	38,1
PBB845-2844	czysty	M16	21,46	24,5	72,24
PBB875-1000	czysty	M16	22,22	25,26	25,4
PBB875	czysty	M16	22,22	25,26	38,1
PBB937	czysty	M16	23,8	26,84	38,1
PBB970	czysty	M16	24,64	27,68	38,1
PBB1000	czysty	M16	25,4	28,44	38,1
PBB1000-2000	czysty	M16	25,4	28,44	50,8
PBB1062	czysty	M16	26,97	30,01	38,1
PBB1062-2000	czysty	M16	26,97	30,01	50,8
PBB1125	czysty	M16	28,58	31,62	38,1
PBB1187	czysty	M16	30,15	33,19	38,1
PBB1250	czysty	M16	31,75	34,79	38,1
PBB1350	czysty	M16	34,29	37,33	38,1
PBB1380	czysty	M16	35,05	38,09	38,1
PBB1500	czysty	M16	38,1	41,14	25,4
PBB1500-1500	czysty	M16	38,1	41,14	38,1
PBB1500-1750	czysty	M16	38,1	41,14	44,45
PBB1625	czysty	M16	41,28	44,32	50,8
PBB1750	czysty	M16	44,45	47,49	50,8
PBB1875	czysty	M16	47,62	50,66	50,8
PBB2000	czysty	M16	50,8	53,84	50,8
PBB2105	czysty	M16	53,47	56,51	50,8